

How do I PAT test 3 phase equipment?

If the three phase equipment has a plug, this can easily be tested with a suitable 230V-415V adaptor. Four are available, that cover 4 or 5 pin - 16A or 32A. Click here to see a list of available adaptors.

If you require more help, please contact us at https://www.seaward.com/gb/enquiry/.